

SITE DETAILS

Lot No.:	Lot 9	Assess No.:	11075
Reserv No.:		Vol/Fol:	1013/213
Dia/Plan:	152182		

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:		Occupied:	Occupied
Public Access:	No		

DESCRIPTION

Walls:	Brick	Roof:	Comugated Iron
Condition:	Good	Integrity:	
Original fabric:	Twin gable section		
Modifications:	Multiple additions over time.		

This brick house has a hipped comugated iron roof which extends to cover the verandah which is supported on timber posts with a decorative frieze between. To the south a separate gable roof covers the main room. The gable end is enclosed with fibro and there is an awning to the window below. To the front facade, the face brickwork is tuckpointed and a rendered band runs at verandah frieze height. A brick chimney punctuates the roofscape. A brick wall with brick columns and pickets with a gate forms the street boundary.

HISTORY

Construction Date:	unknown	Source:	1995 MI
Architect:	Unknown		
Builder:	Unknown		

No History Available.

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
AHC:	4.1.2 Making suburbs



Photo Description:
15/10/1996
Suba & Grundy
Front fence has since been painted white.