



SITE DETAILS

Lot No.:	Lot 34	Assess No.:	11664
Reserv No.:		Vol/Fol:	
Dia/Plan:			

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:			
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls:	Weatherboard/Fibro	Roof:	Comugated Iron
Condition:	Good	Integrity:	
Original fabric:			
Modifications:			

This timber framed weatherboard and fibro clad house has a hipped comugated iron roof with a lean-to roof to a fibro clad extension to the rear and a separate verandah roof to the front elevation. The verandah is supported on metal poles. Windows to the sides are timber framed double hung and there is a rendered brick corbelled chimney to the rear.

HISTORY

Construction Date:	unknown	Source:	
Architect:	Unknown		
Builder:	Unknown		

No History Available.

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
AHC:	4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

The house has aesthetic appeal given that it retains much of its original fabric including its weatherboard cladding and decorative chimney. It is representative of the style of housing of its era and adds to the streetscape of the area.

MANAGEMENT CATEGORY

Management Category: 3
Level of Significance: MODERATE SIGNIFICANCE: Important to the heritage of the locality.
Management Recommendation: Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

"Geraldton: a photographic history", Geraldton Regional Library, 2004.

OTHER PHOTOS



Photo Description:
24/10/1996
Suba & Grundy
Front facade from the street.