



City of Greater Geraldton  
Municipal Inventory of Heritage Places  
Place Record

|                             |                                |             |
|-----------------------------|--------------------------------|-------------|
| Area: Greenough             | Place Number: 80               | Category: 3 |
| Assessment Date: 16/12/1997 | Last Revision Date: 09/03/2005 |             |
| HCWA Number: 13954          | Asset ID:                      | MC H127064  |

PLACE DETAILS

|                |                 |
|----------------|-----------------|
| Name:          | Knapp's House   |
| Other Names:   | Stoke's House   |
| Type of Place: | House           |
| Address:       | Knapps Road     |
| Suburb:        | South Greenough |

LOCATION

|            |         |           |            |          |            |
|------------|---------|-----------|------------|----------|------------|
| Map        | Bookara | GPS       | 6787558.00 | GPS      | 286244.000 |
| Reference: | N.W.    | Northing: | 0000       | Easting: | 000        |



Photo Description:  
9/12/2004  
Henkel  
Front (east) elevation

### SITE DETAILS

|             |        |             |       |
|-------------|--------|-------------|-------|
| Lot No.:    | Lot 11 | Assess No.: | 64090 |
| Reserv No.: |        | Vol/Fol:    |       |
| Dia/Plan:   |        |             |       |

### USE OF PLACE

|                |           |           |              |
|----------------|-----------|-----------|--------------|
| Original Use:  | Residence |           |              |
| Current Use:   | Residence |           |              |
| Ownership:     |           |           |              |
| Public Access: | No        | Occupied: | Not Occupied |

### DESCRIPTION

Walls: Limestone                      Roof: Comugated Iron  
Condition: Fair                      Integrity:  
Original fabric:  
Modifications:

Set well of Brand Highway at the foot of the sandhills, this four-roomed stone house has a gambrel comugated iron roof which extends to cover the front (east) verandah. The house features painted random rubble stonework which is pointed to the front facade. Openings and comers are enhanced by brick quoining. Access to the house is via 5 brick steps

