



City of Greater Geraldton  
Municipal Inventory of Heritage Places  
Place Record

|                             |                                |             |
|-----------------------------|--------------------------------|-------------|
| Area: Mullewa               | Place Number: 41               | Category: 4 |
| Assessment Date: 23/03/1995 | Last Revision Date: 23/03/2012 |             |
| HCWA Number: 5107           | Asset ID: MCH126647            |             |

PLACE DETAILS

|                |   |
|----------------|---|
| Name:          | Devil's Creek Farmhouse                         |
| Other Names:   | 36 Francis Street                               |
| Type of Place: | Farmhouse                                       |
| Address:       | Devil's Creek Road, South side near western end |
| Suburb:        | Devils Creek                                    |

LOCATION

|                |       |               |            |              |            |
|----------------|-------|---------------|------------|--------------|------------|
| Map Reference: | 14.15 | GPS Northing: | 6829000.00 | GPS Easting: | 348800.000 |
|                |       |               | 0000       |              | 000        |

### SITE DETAILS

|             |          |             |      |
|-------------|----------|-------------|------|
| Lot No.:    | Lot 4610 | Assess No.: | 1235 |
| Reserv No.: |          | Vol/Fol:    |      |
| Dia/Plan:   |          |             |      |

### USE OF PLACE

|                |          |           |          |
|----------------|----------|-----------|----------|
| Original Use:  | Famhouse |           |          |
| Current Use:   | Famhouse |           |          |
| Ownership:     |          |           |          |
| Public Access: | No       | Occupied: | Occupied |

### DESCRIPTION

|                  |       |            |     |
|------------------|-------|------------|-----|
| Walls:           | Stone | Roof:      | CGI |
| Condition:       | Good  | Integrity: |     |
| Original fabric: |       |            |     |
| Modifications:   |       |            |     |

The Consultant was unable to gain access to the property to undertake an assessment during the 2011 MHI review. The following description is

