



City of Greater Geraldton
Municipal Inventory of Heritage Places
Place Record

Area: Geraldton	Place Number: 155	Category: 6
Assessment Date: 15/10/1996	Last Revision Date: 04/11/2009	
HCWA Number: 13405	Asset ID: MC H126989	

PLACE DETAILS

Name:	Site
Other Names:	118 Fitzgerald Street
Type of Place:	Site
Address:	118 Fitzgerald Street
Suburb:	Geraldton

LOCATION

Map Reference:	14.14	GPS Northing:	6813862.00	GPS Easting:	266482.000
			0000		000



Photo Description:
15/10/1996
Suba & Grundy
Steeply pitched roof was a feature.

SITE DETAILS

Lot No.:	Lot 17	Assess No.:	11085
Reserv No.:		Vol/Fol:	
Dia/Plan:			

USE OF PLACE

Original Use:	Residence	Occupied:	Occupied
Current Use:	Not Applicable		
Ownership:			
Public Access:	No		

DESCRIPTION

Walls:	Weatherboard/CGI	Roof:	Comugated Iron
Condition:	Fair	Integrity:	
Original fabric:			
Modifications:			

This house was demolished in 2005. The following description was contained in the 1997 Municipal Inventory: This small timber framed cottage has a steeply pitched hipped painted comugated iron roof with comugated iron cladding to the side walls and weatherboard to the front (east) facade. A separate verandah roof to the front elevation is supported on timber posts with a trellis balustrade and fibro infill to the verandah ends. Windows are timber framed and double hung. To the rear a lean-to roof covers a fibro clad extension.

HISTORY

Construction Date:	1890	Source:	Feilman
Architect:	Unknown		
Builder:	Unknown		

The house was demolished in 2005.

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
	300 Occupations
AHC:	4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

There were few examples remaining of this simple style of corrugated iron and weatherboard clad cottage. Further, this place had high integrity and its form contributed to the streetscape of the area.

1997 Management Category: 3. SIGNIFICANT AS AN INDIVIDUAL BUILDING. Retain and conserve if possible: endeavour to conserve the significance of the place through provisions of the Town Planning Scheme. Photographically record the place prior to any major redevelopment.

MANAGEMENT CATEGORY

Management Category: 6

Level of Significance: MUNICIPAL INVENTORY ARCHIVE: Place was previously included in the Municipal Inventory but has been removed due to demolition or diminished heritage significance.

Management Recommendation: The place does not form part of the relevant local Town Planning Scheme Heritage List. This category is for record keeping purposes only.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

Bibliography: