



City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton	Place Number: 65	Category: 6
Assessment Date: 05/12/1996	Last Revision Date: 06/10/2009	
HCWA Number: 13249	Asset ID: MCH126819	

PLACE DETAILS

Name:	Site
Other Names:	264 Chapman Road
Type of Place:	Site
Address:	264 Chapman Road
Suburb:	Beresford

LOCATION

Map Reference:	15.17	GPS Northing:	6817118.00	GPS Easting:	267434.000
			0000		000




Photo Description:
28/08/2007
Rod Milne
House demolished in 2009.

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
AHC:	4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

Although the verandahs have been enclosed the house still retains much of its original character and consequently contributes to the built environment of the locale. 1997 Management Category: 5. SIGNIFICANT IN CONTRIBUTING TO LOCAL CHARACTER. Significant but not essential to an understanding of the history of the district. Photographically record the place prior to any major redevelopment.

MANAGEMENT CATEGORY

Management Category:	6
Level of Significance:	MUNICIPAL INVENTORY ARCHIVE: Place was previously included in the Municipal Inventory but has been removed due to demolition or diminished heritage significance.
Management Recommendation:	The place does not form part of the relevant local Town Planning Scheme Heritage List. This category is for record keeping purposes only.

OTHER LISTINGS

No other listings



Photo Description:
5/12/1996
Suba & Grundy
West (front) facade.