



City of Greater Geraldton
Municipal Inventory of Heritage Places
Place Record

Area: Geraldton	Place Number: 397	Category: 3
Assessment Date: 05/11/1996	Last Revision Date: 16/03/2010	
HCWA Number: 13791	Asset ID: MCH127081	

PLACE DETAILS

Name:	House
Other Names:	27A Urc h Street
Type of Place:	House
Address:	27A Urc h Street
Suburb:	Beresford

LOCATION

Map Reference:	15.17	GPS Northing:	6816088.00	GPS Easting:	267304.000
			0000		000



Photo Description:
6/08/2008
Tanya Henkel
House set behind front brick wall.

SITE DETAILS

Lot No.:	Lot 2	Assess No.:	12634
Reserv No.:		Vol/Fol:	
Dia/Plan:			

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:	Shire of Greenough		
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls:	Weatherboard/Fibro	Roof:	Comugated Iron
Condition:	Not applicable	Integrity:	
Original fabric:			
Modifications:			

Located on one block and situated behind a high brick wall these two timber framed houses have a hipped comugated iron roof and are clad with fibro and weatherboard. A separate hipped verandah roof covers each of the front verandahs which have some fibro infill. Windows are timber framed and double hung. To the rear each building has a fibro clad lean-to and to the side each has a metal chimney. (see 27B Urch Street.)

HISTORY

Construction Date:	unknown	Source:	Plaque
Architect:	Unknown		
Builder:	Unknown		

No History Available.

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision 400 Social and civic activities
AHC:	4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

These weatherboard dwellings are representative of the style of housing of their era. Although sited behind a tall brick wall the roof style of the place is still evident and as such makes a contribution to the streetscape of the area

MANAGEMENT CATEGORY

Management Category: 3

Level of Significance: MODERATE SIGNIFICANCE: Important to the heritage of the locality.

Management Recommendation: Conservation of the place is recommended.

Any proposed change to the place should not unduly impact on the heritage values of the

B a




Photo Description:
5/11/1996
Suba & Grundy
Two houses behind brick wall.